

~~TAS~~ ~~SECRET~~ ~~CONFIDENTIAL~~ ~~PSC-148~~
~~JCF~~ ~~FILE~~ ~~PSC-148~~
 DISPATCH TO
 FIELD

January 18, 1954

25X1

25X1
ZSAI

Subject: (Correction to instruction book addendum for RS-6)
 radio set contract PSC-148-UNV

Dear [redacted]:

25X1

We would like to call to your attention at this time that an error has been found on Page 10 of the subject addendum dated May 15, 1953. Since this is an insignificant change so far as the hand book is concerned we did not deem it necessary to revise this document, however, it was felt that your organization should be advised of this discrepancy. The six female contact plug connectors identified with symbol number S08 is shown as part number 409A122. This part number is incorrect and should read our part number 409B175.

No action by you is expected as this is being sent to you in the way of information only.

Very truly yours,

25X1

CPN/bf

THS- will you check and see how many addenda (if any) are being sent out in RS-6 Instr. Books. If none see if you can locate (thru Harvey's group) the addenda. TNX JB 3/1/54

ILLEGIB

Sanitized Copy Approved for Release 2011/09/20 : CIA-RDP78-03424A002400020057-3